



Normal Conducting Linac RF Performance & Challenges

Mark Crofford

Accelerator Advisory Committee

March 24-26, 2015



RF Systems – Outline

- Introduction to the discussion on the normal conducting Linac
- Ion Source RF
- MEBT Rebuncher System
- DTL Circulators
- CCL Klystrons
- Klystron Spares & Vendor Engagement
- Transmitter Issues and Improvements
- LLRF
- DTL & CCL RF Window Status
- Downtime Overview
- Summary

Introduction to the Discussion on Normal Conducting Linac

- RF systems reliability is sufficient to achieve neutron production availability >90%.
- Recovery from RF faults in the NC Linac is significantly longer than in the SC Linac due to the long thermal time constants of the copper structures and cooling systems
 - 20-30 minutes compared to a few minutes
- RF faults in the NC Linac are correlated with (or caused by):
 - voltage breakdown (arcing) at RF windows and/or within the cavity
 - vacuum degradation (bursts of outgassing)
 - inadequate vacuum pumping capacity
 - beam loss and, perhaps, field emission and/or multipacting
 - glitches in water flow and vacuum interlocks
 - excessive resonance error

Ion Source RF

- The 2 MHz QEI amplifier continues to operate at ground potential outside of the 65 kV enclosure.
 - Only downtime was attributed to a failed connection on the output circuit
- The 2 MHz isolation transformer has required minimal maintenance since installation in July 2010
- The Tektronix generator/control system has been trouble-free
 - Implemented a frequency shift mode to better support plasma ignition
- Use of the Tomco 2 MHz, 120 kW solid-state amplifier has been successful on the test stand
 - The VSWR circuit was modified to improve reflected power operation
 - A second Tomco solid-state amplifier is installed on the ITSF
 - Desire to gain further experience before its use on the production ion source

MEBT Rebuncher System

- MEBT Rebuncher RF amplifiers were upgraded in September 2010 to solid-state devices
- The amplifiers have performed well and cause minimal downtime
 - We have recently experienced two 4.2 kW amplifier module failures
 - One power supply has failed
 - One intermittent cable connection



MEBT Rebuncher Cavities

- MEBT chopper target failure resulted in water in the MEBT rebuncher cavities
 - All cavities required RF reconditioning
 - After reassembly the MEBT 3 tuner assembly developed a vacuum leak in the bellows
 - MEBT 1 field probe developed a vacuum leak
- Lack of cavity spare components was noted
 - Fabricated spare field probes
 - Cleaned and conditioned a spare fundamental power coupler
 - Procured C-seals for a cavity rebuild (if required)
 - Working to procure/repair a spare tuner assembly

DTL Circulator Issues

- Arcing was detected in the DTL-6 circulator on June 16th, 2014
- A leak was detected on the bottom pancake of the circulator assembly
- A spare circulator was removed from the RFTF test stand and installed to allow for continued operations
 - No unused spares were available
- Inspections of the remaining 6 circulators revealed similar issues with all installed devices
 - Some show significant corrosion



DTL Circulator Issues (cont.)

- Issue was isolated to the O-ring seals between the water inlet & outlet connections on the pancakes
- AFT was consulted and performed an on-site repair of the failed circulator and provided training on the repair techniques
- Three spare 402.5 MHz circulators are on order



CCL Klystron Failures

- Three of the four original Thales 5 MW klystrons have failed within 1 year
 - Two klystrons failed on filament open failures (CCL 2&3)
 - One klystron is unable to generate RF power above 3.5 MW (CCL4)
 - Operating hours for the failed klystrons range from 51000 – 57000 hours
 - The remaining original klystron is still in service and the emission curve has not shown degradation
 - The average time to replace a CCL klystron is 14 hours
 - A Thales 5 MW klystron is staged in the klystron gallery ready for installation



High Power Amplifier Inventory

Type	Application	Frequency	Peak Power	Vendor	Installed	Spare
Solid-State	MEBT Rebunchers	402.5 MHz	25 kW	Tomco	4+1*	a few modules
Klystron	RFQ, DTL	402.5 MHz	2.5 MW	E2V & Thales	7+2**	5 4 (2***)
Klystron	CCL	805 MHz	5 MW	Thales	4+1**	6 3 (2***)
Klystron	SCL	805 MHz	550-700 kW	CPI & Thales	81	51 57
Tetrode	Accumulator Ring	1 & 2 MHz	500 kW	Thales & CPI	4	4

Notes:

- E2V discontinued their production and support of the 2.5 MW klystrons; Thales developed a plug-compatible replacement (3 delivered).
- Thales is presently assisting with oscillation of one 5 MW klystron.
- Of the 57 spare 550-700 kW klystron, 12 are Thales

Key:

- * hot spare
- ** test stand
- *** ready

Klystron Lifetime and Vendor Engagement

- The majority of the klystrons presently used in the Linac have about 60,000 hours of run time.
 - lifetimes approaching 100,000 hours are likely, but uncertain
 - one cathode-based failure & 3 filament-based failures to date
 - More attention to cycling of the filaments to maximize lifetime
- Cathode emission data being collected to assist in monitoring and predicting lifetimes.
 - Data utilized to adjust filament settings to maximize cathode life
- E2V provided original 402.5 MHz klystrons; Thales has produced plug-compatible replacements.
 - Thales has produced every flavor of klystron or tube presently utilized at SNS.

Vendor Engagement (cont.)

- CPI produced the vast majority of the SC Linac klystrons
 - We have recently received 6 new 700 kW klystrons
 - Completed the 1st rebuild of a failed 550 kW, 805 MHz klystron
 - CPI has expressed interest in producing 5 MW 805 MHz & 2.5 MW 402.5 MHz klystrons
- Thales quality has been less than ideal
 - Final two 5 MW klystrons delivered have required vendor involvement
 - One klystron experienced oscillations above 3.8 MW
 - One klystron required extensive conditioning
 - Reluctant to support rebuild of failed klystrons. The quoted price to rebuild was 97% of the price of a new tube.
 - Vacuum issues experienced with the recently delivered spare production RF windows

Transmitter Issues & Improvements

- The magnet power supplies in the warm linac transmitters have been updated
 - Use of COTS supplies – reduced costs
 - Lowered the temperature in the hottest rack by $\sim 18^{\circ}$ F
- Replaced low-flow flowmeters with ultrasonic meters
 - Minimize nuisance trips
- Significant increase of solid-state amplifier failures
 - Majority of the failures are traced to the power supply
 - Implemented on-site repair and testing program

Filament Power Supply Issues

- Fourteen filament power supplies have failed since last AAC review
 - 53 filament power supplies are installed
- Vendor involvement discovered a series of defective parts with the same date-code
 - Waiting for detailed failure analysis from vendor
 - Repaired and returned to the SNS
- Development of a stand-alone test stand is underway for improved bench testing
 - Allows for a realistic test without cycling of actual klystron filaments

Transmitter Temperature Measurement System

- Installed temperature measurement system to monitor critical chassis temperatures
- Currently installed in Warm Linac & four SCL racks
 - Rack temperatures were unavailable
 - Supports troubleshooting



RF Range, DTL_HPRF 4			402.5 MHz
	Present	High Limit	Status
SSA Input FWD	-2.48 dBm		
SSA Output FWD	43.81 W	170.00 W	Ok
SSA Output REFL	2.11 W	17.00 W	Ok
SSA Gain	48.90 dB		
SSA Temperature			Ok
Rack Ambient Temp.	90.8 F		
Filament PS Temp.	89.2 F		
Mag PS 1 Temp.	101.4 F		
Mag PS 2 Temp.	91.8 F		
Window A Temp.	Not Used	CCL Only	
Window B Temp.	Not Used		
Klystron Input FWD	36.48 W		
Klystron Input REFL	0.26 W		
Klystron Output FWD	2310.29 kW	2700.00 kW	Ok
Klystron Output REFL	18.82 kW	50.00 kW	Ok
Klystron Gain	48.02 dB		
Status		Main Breaker	Closed
Timing Pulse	Enabled	RF Switch	To SSA
Delay	0.53 ms	Faults	No Faults
RF Data Com		Mode	Rad. For HV
SSA Gate	Ok		
	Ok		

Buttons: HPRF, Fil. Off, Fil. On, Stop, Reset

LLRF Performance & Issues


- The LLRF system continues to operate within specification
- The adaptive feed-forward is sufficient but the learning time of the algorithm could be improved
- The output amplifier IC for the RF output circuit has shown issues with the bond wires
 - multiple failures in the past year
 - All amplifier ICs are being replaced during the calibration cycle of the system
- System has several obsolete components to include the FPGAs
 - Adequate spares are available
 - Resources will be needed to redesign in the future

DTL & CCL RF Vacuum Windows

- No DTL or CCL window failures since July 2012
 - Improved RF conditioning techniques
 - Increased attention to detail
- DTL Window Status
 - Six DTL windows are in use
 - Two windows are processed and stored under vacuum
 - Two new windows have been purchased (TH20616)
 - The windows arrived with vacuum issues and were returned for repair
 - One new prototype window has been tested and fully conditioned
- CCL Window Status
 - Eight CCL windows are in use
 - Two windows are processed and stored under vacuum
 - Six new windows have been received and are scheduled for testing and RF processing
 - One window was returned to the manufacturer for repair
 - One new prototype window is currently under test

RF Downtime – May2013 to Present

- Total Downtime 265 hours out of 10303 scheduled Accelerator Physics/Neutron Production hours (2.57%)



RF Downtime (cont.)

- Occasional major event quickly adds to the system downtime but this is only ~20% of the total RF downtime
 - DTL 6 circulator failure – 17 hours (June 2014)
 - CCL2 klystron failure – 14 hours (May 2014)
 - CCL3 klystron failure – 16 hours (Oct 2014)
- Majority of trips are ~ 20 – 30 minutes in duration
 - Cavity and window arcing
 - Vacuum excursions/bursts
- Overall reliability of the RF systems is very good
 - Continue to seek ways to improve the systems

Summary

- RF systems reliability is sufficient to achieve neutron production availability >90%
- Starting to see an increase in system failures, we need to continue to seek alternative COTS solutions
- Reasonable supply of klystrons but we would like to engage with CPI for the high power klystrons
- Implementation of better RF conditioning practices have paid off with no new broken RF windows